

TOOL MODEL MT-3

PRESSURE/TORQUE CONVERSION CHART

Standard Torque Chart

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

1200	512
1400	598
1600	683
1800	768
2000	860
2200	939
2400	1025
2600	1110
2800	1195
3000	1281
3200	1366
3400	1470
3600	1537
3800	1661
4000	1708

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

4200	1793
4400	1922
4600	1980
4800	2061
5000	2154
5200	2243
5400	2333
5600	2425
5800	2515
6000	2603
6200	2690
6400	2777
6600	2864
6800	2952
7000	3039

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

7200	3144
7400	3212
7600	3297
7800	3381
8000	3508
8200	3588
8400	3686
8600	3751
8800	3857
9000	3915
9200	4012
9400	4122
9600	4216
9800	4318
10000	4406